INSPECTION REPORT

Partial XXX Complete Exploration
Inspection Date: 01/24/2003 Time: 10:00 am-12:30 pm
Date of Last Inspection: 12/11,13/2002

Mine Name: Horizon Mine	County: Carbon	Permit Number: <u>C/007/020</u>				
Permittee and/or Operator's Name: Lodestar Energy, Inc.						
Business Address: HC 35 Box 370, Helper, Utah 84526						
Company Official(s): Rodney Head, Safety						
State Official(s): Stephen J. Demczak	_Federal Official(s):	None				
Weather Conditions: Cooled, Cloudy, 30's, Snow Covered						
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther				
Existing Acreage: Permitted 711 Disturbed 9 Regraded Seeded Seeded						
Status: Active						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS			Ĺĺ	Ĺĺ
3.	TOPSOIL			Ĺĺ	Ĺĺ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<u>[X]</u>		[X] [X]	Ĺĺ
c.	OTHER SEDIMENT CONTROL MEASURES				
d.	WATER MONITORING				\Box
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES				\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		[X]	
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION				
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL				
15.	CESSATION OF OPERATIONS	[X]		[X]	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				\Box
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	
19.	AVS CHECK (4 th Quarter- April, May, June)				
20.	AIR QUALITY PERMIT				
21.	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/020</u> DATE OF INSPECTION: <u>01/24/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The CTS system was reviewed on January 31, 2003 for the Horizon Mine. The Legal and Financial information is the only permitting action outstanding. This information has not been submitted to the Division at this time. The permittee is in the process of gathering this information.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The Diversions were spot-checked and contained some ice and snow. The snow was intermittent throughout the ditches, with water flowing under the snow cover. The diversions were flowing water as designed.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was inspected with no hazardous conditions noticed. The sediment pond did contain water but was not discharging.

The mine was discharging mine water during the inspection. The mine water by passes the sediment pond and is an UPDES point source discharge.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee did not have any refuse at the mine; however, there was a small pile of high ash coal located next to the sediment pond.

8. NONCOAL WASTE

The area was generally clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The mine was idle. There is no anticipated time to start-up production.

No new surface facilities are under construction.

Inspector's Signature:			Date:	January	31,	2003
	Stephen J. Demczak	#39		•		

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
David Miller, Lodestar
Price Field office
O:\007020.HZN\Compliance\2003\p_0124.doc